


Hazen



North Metropolitan Sewer Sections 4, 5, 6, and 186 Study

LiDAR Scanning and Strategies to Guide Rehabilitation Planning

January 28, 2019



About the NMS...

- 120 (+/-) years old
- Conveys flow to the Winthrop Terminal Facility (135 MGD during wet weather)
- Two previous rehabilitation efforts



And then this happened...

- Large piece of plastic discovered on inlet screen to Winthrop Terminal
- MWRA video inspection unit locates source
- Contractor hired to remove additional loose liner



- Videos showed peeling epoxy liner
- Contractor noted shotcrete was soft in places
- The only way to understand extent of the issue was a manned inspection and internal scan
- RFQP issued



Project Location




Data SIO, NOAA, U.S. Navy, NGA, GEBCO



Google Earth

Representative Pipe Cross Sections


Circular Shape



Dome Shape




Horseshoe Shape






1980s – CCTV Inspection




- Sewer constructed in 1890s
- Bricks missing
- Infiltration
- Deteriorating mortar






1992 – Phase 1 Rehabilitation





- 3,200 LF
- 5-6" shotcrete
- Wire mesh for structural support
- **60 mil epoxy coating**





1994 or 1995

Epoxy delamination



1890

1995




2011





1995 – Phase 2 Rehabilitation

- 10,500 LF
- 3-4" shotcrete
- 8% microsilica (MS)
- No epoxy coating



Existing Condition - Investigations

- Pipe and Manhole inspections
 - CCTV (PACP)
 - Pipe walk and sounding
 - Petrographic Testing
 - LiDAR
- Hydraulics
- Corrosion
- Permitting
- Real estate/easements
- Project coordination



CCTV Review – Liner and Surface Defects



Liner delamination

Condition of shotcrete?



Surface spalling

CCTV Review – Reinforcing Steel Exposed



~35 LF of exposed rebar




~25 LF of exposed rebar

Pipe Walk and Soundings




LiDAR - Light Detection and Ranging

Typical LiDAR section (1 foot)




LiDAR

Careful QC is required





Several feet of shotcrete?




LiDAR Overlay of NMS


Adjustment of results



LiDAR



Phase I Rehabilitation




Phase II Rehabilitation


Core Samples and Petrographic Analysis

17 core samples subjected to petrographic analysis

- 4 in Phase I shotcrete (spec'd at 5" to 6")
- 13 in Phase II shotcrete (spec'd at 3" to 4")




Core at STA S004 0002+62 (spec'd at 6")



Core at STA S004 0048+32 (spec'd at 3")

Other Evaluations

- Hydraulic capacity evaluation
- Bypass pumping
- Corrosivity
- Traffic assessment
- Permitting
- Project coordination



Pipe Rehabilitation - Considerations

- Proven fully structural solution with 50-year design life
- Bypass pumping requirements
- Pipe surface preparation requirements
- Construction impacts on Winthrop residents and businesses
- Corrosion resistance



Rehabilitation Options

- Cured-In-Place Pipe (CIPP) lining
- Slip-lining / Segmental lining
- Spiral-wound lining
- Spot repairs:
 - Fiber Wrap
 - Chemical grouting
 - Joint seals
- Spray-on linings:
 - Epoxy and Polyurethane
 - Cementitious
 - Geopolymer





Methods not recommended

Technology	Reasons			
CIPP	<i>Full Bypass</i>	<i>Styrene cure water</i>	<i>Wet-out facilities</i>	<i>Excessive cure time</i>
Spray-on (over degraded shotcrete)	<i>Surface preparation would be impractical and unsafe</i>	<i>Not fully structural</i>	<i>Internal bypass</i>	<i>QA/QC inspection in NMS</i>
Spiral wound	<i>Radii smaller than can be navigated</i>	<i>Wet weather flows would make nearly infeasible</i>	<i>Varying amounts of bypass</i>	
Point Repair (Fiberwrap)	<i>Full Bypass</i>	<i>Surface preparation would be impractical</i>	<i>Not proven</i>	

Recommended Methods



Technology	Reasons			
Slip-lining	<i>Bypass pumping not needed</i>	<i>Fully structural</i>	<i>Corrosion resistant pipe</i>	<i>Many straight runs lends itself to slip-lining</i>
Segmental lining (25' of exposed rebar)	<i>Structural repair (wire mesh is likely already compromised)</i>	<i>Prevent further corrosion</i>		
Spray-on (over exposed steel)	<i>Prevent corrosion / rust of exposed steel</i>	<i>Shotcrete with MS has been proven within the NMS</i>	<i>Potentially improve flow hydraulics</i>	
Chemical grout	<i>Infiltration should be stopped to prevent sinkholes</i>		<i>Infiltration must be stopped before spray-on lining of steel pipe</i>	
Internal Joint Seal	<i>Infiltration in sand catcher chamber might be too heavy for chemical grouting</i>			

Recommendations



- Legend**
- Priority 1 Localized Repairs
 - Steel Wye
 - Priority 1 Sliplining
 - Sewer Line

Recommendations



Conclusion

- Use of advanced condition assessment tools: effective, but requires careful QC and understanding
- Fully utilize institutional knowledge
- Complete understanding of project environment results in better planning
- Full market analysis of rehabilitation technologies required