

RUNNING BETWEEN RAINDROPS: Corrosion Repair of a Critical CSO Pump Discharge Pipe

Alejandro Alvarez

Construction Coordinator


**Massachusetts Water
Resources Authority**

Kevin R. Krawiec, PE

Principal Structural Engineer

Corrosion Probe, Inc.






MWRA PRISON POINT CSO (PPCSO)

- Began operation 1981
- 7 Education Way, Cambridge









MWRA PRISON POINT CSO (PPCSO)

- Dry weather
 - Screening
 - Pumping
 - 1-2 MGD
- Wet weather
 - Screening
 - Disinfection
 - Detention
 - Dechlorination
 - 323 MGD capacity





Facility Plan





PUMP ROOM SECTION





Discharge Header (Existing Condition)





The Problem

Coating Failure and Carbon Steel Corrosion



External: Isolated



Internal: General






The Problem

- Ongoing perforation & leakage
- External welded patch plate repairs





Initial Assessment – External UT

MANIFOLD PIPING UT READINGS											
Location	Pipe Diam.	Circumferential Position on Pipe (Looking in Direction of Flow)								Avg.	Min.
		12:00	1:30	3:00	4:30	6:00	7:30	9:00	10:30		
S1-UF	42"	0.293	0.181	0.221	0.245	0.214	0.240	0.227	0.217	0.230	0.181
S1-DF	42"	0.104	0.189	0.268	0.236	0.227	0.214	0.072	0.202	0.189	0.072
S1-L	42"				0.243		0.242				
S1-M	42"				0.242		0.243			0.242	0.239
S1-R	42"				0.242		0.239				
Y	42"	0.315	0.184	0.221	0.233	0.198	0.240	0.266	0.246	0.238	0.184
CC	42"	0.097	0.078	0.267	0.112	0.271	0.336	0.251	0.232	0.206	0.078
S2-UF	42"	0.124	0.246	0.268	0.270	0.072	0.075	0.277	0.239	0.196	0.072
S2-DF	42"	0.294		0.273	0.283	0.230	0.311	0.271	0.077	0.248	0.077
S2-L	42"				0.314		0.290				
S2-M	42"				0.267		0.070			0.257	0.070
S2-R	42"				0.287		0.312				
D	42"	0.312	0.297	0.292	0.296	0.311	0.324	0.245	0.255	0.292	0.245
P	42"					0.268				0.272	0.264
						0.264					
						0.283					
DD	42"	0.081	0.147	0.075	0.097	0.090	0.334	0.079	0.078	0.123	0.075
E	42"-72"	0.242	0.226	0.250	0.292	0.233	0.320	0.236	0.235	0.235	0.226
EE	42"-72"	0.217	0.212	0.265	0.218	0.266	0.112	0.274	0.199	0.220	0.112
Q	42"-72"					0.261	0.221			0.246	0.205
						0.267	0.254				
						0.205	0.265				
V	42"-72"			0.258						0.260	0.258
				0.260							
				0.261							
R	42"-72"						0.178			0.185	0.172
							0.172				
							0.206				
FF	42"-72"	0.094	0.209	0.270	0.264	0.075	0.284	0.336	0.214	0.218	0.075
GG	72"	0.125	0.182	0.258	0.287	0.286	0.296	0.100	0.169	0.213	0.100
KK	72"	0.253	0.182	0.091	0.299	0.164	0.267			0.209	0.091
LL	72"	0.253	0.166	0.106	0.102	0.274	0.286	0.236	0.193	0.202	0.102
S3-UF	72"	0.101	0.135	0.074	0.230	0.232	0.240	0.239	0.215	0.183	0.074
S3-DF	72"	0.110	0.233	0.085	0.065	0.277	0.299	0.248	0.232	0.194	0.065
S3-L	72"				0.295		0.300			0.216	0.066
S3-M	72"				0.067		0.258				
S3-R	72"				0.066		0.311				
G	72"	0.299	0.243	0.230	0.297	0.194	0.322	0.239	0.249	0.259	0.194
MM	72"-96"	0.210	0.192	0.180	0.106	0.154	0.331	0.191	0.190	0.194	0.106
							0.312	0.203			
S	72"-96"						0.312	0.204		0.257	0.200
							0.311	0.200			
H	72"-96"	0.187	0.221	0.219	0.260	0.312	0.297	0.110	0.157	0.220	0.110
NN	72"-96"	0.182	0.210	0.233	0.296	0.315	0.305	0.195	0.195	0.241	0.182
						0.310					
T	72"-96"					0.318				0.314	0.310
W	72"-96"			0.217						0.217	0.216
				0.216							
				0.217							
OO	72"-96"	0.147	0.229	0.255	0.298	0.327	0.135	0.177	0.175	0.218	0.135
I	96"	0.259	0.224	0.233	0.265	0.290	0.317	0.276	0.253	0.265	0.224
RR	96"	0.224	0.205	0.245	0.072	0.092	0.315			0.189	0.072
K	96"	0.224	0.233	0.209	0.259	0.332	0.270	0.218	0.217	0.245	0.209
SS	96"	0.240	0.205	0.078	0.305	0.243	0.112	0.199	0.185	0.196	0.076
S4-UF	96"	0.163	0.065	0.100	0.267	0.075	0.259	0.091	0.102	0.140	0.065
S4-DF	96"	0.146	0.117	0.198	0.252	0.078	0.112	0.102	0.189	0.149	0.078
S4-L	96"				0.109		0.131			0.163	0.109
S4-M	96"				0.116		0.258				
S4-R	96"				0.254		0.112				
L	96"	0.263	0.212	0.221	0.302	0.330	0.268	0.204	0.227	0.253	0.204
		0.122									
U	96"	0.116								0.119	0.116
		0.120									
N	96"	0.273	0.262	0.230	0.289	0.318	0.302	0.261	0.276	0.276	0.230

DISCHARGE PIPING UT READINGS											
Location	Pipe Diam.	Circumferential Position on Pipe (Looking in Direction of Flow)								Avg.	Min.
		12:00	1:30	3:00	4:30	6:00	7:30	9:00	10:30		
PUMP NO. 1 DISCHARGE											
A	36"	0.257	0.227	0.196	0.221	0.217	0.218	0.220	0.220	0.222	0.196
O	36"-42"							0.219		0.223	0.219
								0.228			
								0.223			
B	36"-42"	0.251	0.217	0.207	0.231	0.242	0.227	0.220	0.246	0.230	0.207
AA	42"	0.147	0.173	0.227	0.249	0.215	0.262	0.184	0.187	0.206	0.147
C	42"	0.243	0.223	0.232	0.226	0.215	0.243	0.212	0.211	0.226	0.211
BB	42"	0.116	0.187	0.218	0.261	0.194	0.262	0.108	0.210	0.195	0.108

Value less than minimum thickness for allowable hoop stresses

Value less than 0.125-inch

Original: 1/4" (0.250)
5/16" (0.313)

PUMP NO. 2 DISCHARGE											
Location	Pipe Diam.	12:00	1:30	3:00	4:30	6:00	7:30	9:00	10:30	Avg.	Min.
JJ	48"	0.073	0.127	0.121	0.327	0.091	0.299	0.271	0.122	0.179	0.073
F	48"	0.232	0.151	0.202	0.235	0.265	0.251	0.162	0.209	0.213	0.151
II	48"	0.113	0.190	0.293	0.309	0.081	0.106	0.267	0.205	0.196	0.081
HH	48"	0.163	0.152	0.125	0.258	0.261	0.248	0.091	0.218	0.190	0.091

Corroded: 0.222 ave.
0.065 min.

PUMP NO. 3 DISCHARGE											
Location	Pipe Diam.	12:00	1:30	3:00	4:30	6:00	7:30	9:00	10:30	Avg.	Min.
QQ	48"	0.305	0.112	0.125	0.128	0.234	0.299	0.096	0.321	0.203	0.096
J	48"	0.303	0.305	0.262	0.303	0.205	0.302	0.276	0.281	0.280	0.305
PP	48"	0.298	0.107	0.165	0.239	0.303	0.308	0.115	0.245	0.223	0.107

PUMP NO. 4 DISCHARGE											
Location	Pipe Diam.	12:00	1:30	3:00	4:30	6:00	7:30	9:00	10:30	Avg.	Min.
TT	48"	0.217	0.176	0.230	0.078	0.205	0.256	0.209	0.074	0.181	0.074
M	48"	0.188	0.202	0.254	0.163	0.182	0.249	0.226	0.187	0.206	0.163
							0.340	0.281	0.249		
							0.320	0.234	0.200		
X	48"						0.346	0.283	0.251	0.278	0.200





Initial Assessment

- Structural Analysis
 - Allowable minimum thickness: 1/8" (0.125)
 - Overstressed at pipe saddles






Initial Assessment

- Chloride source:
 - Roadway deicing salts
 - Salt water backfill
- Oxygen source: Post-operation draining:
- Cyclic use
 - Drained: Corrosion formation
 - Operated: Corrosion removal
 - Fresh metal exposure

Erosion Corrosion Mechanism





Rehabilitation Challenges

- Operable with 12-hour notice
- No bypass
- 20-inch manhole
- Tidal inflow
- Welded pipe
- Clearances
- Identifying thinned areas





Phase I Rehab


- Welded leak patches
- External UT & patches at thinned areas
- Pipe saddle enlargement
- Exterior coating






Phase II Rehab Design


Tidal inflow: Double block & bleed





Phase II Rehab Design

Access: 2 new manholes







Phase II Rehab Design

Repair

- Initial abrasive blasting
- Structural inspection
- Welded repairs
 - Patch plates
 - Pit welding
 - Joint welding
 - Magnetic particle testing





Phase II Rehab Design

Protection

- Internal epoxy pit filler & 150-mil liner
- External weld damage touch-up
- Testing
 - Chlorides
 - Profile
 - Wet, dry film thickness
 - Adhesion
 - Holiday






Phase II Rehab Design

Work restrictions (Running between raindrops)

- Dry weather: Interior and exterior
- Wet weather expected: Exterior only
- Activation: No work
- Demobiliation
 - Partial: daily
 - Full: Weekend and wet weather






Phase II Rehab Construction



Manhole Installation



Phase II Rehab Construction



Initial abrasive blasting





Phase II Rehab Construction



Structural Inspection: Visual





Phase II Rehab Construction



Structural Inspection: Visual







Phase II Rehab Construction



Structural Inspection: Ultrasonic Thickness



Phase II Rehab Construction




Structural Inspection: Repair definition





Phase II Rehab Construction




Structural Inspection: Repair definition





Phase II Rehab Construction





Structural Inspection: Repair definition





Phase II Rehab Construction




Structural Inspection: Plate location





Phase II Rehab Construction



Structural Inspection: Joint weld location





Phase II Rehab Construction



Structural Inspection: Crotch plate location





Phase II Rehab Construction



Welded Repairs





Phase II Rehab Construction



Weld repairs: External patch plates





Phase II Rehab Construction



Weld repairs: Internal patch plates





Phase II Rehab Construction




Weld repairs: Internal pit & joint





Phase II Rehab Construction



Weld repairs: Discharge crotches






Phase II Rehab Construction




Activation Leaks







Phase II Rehab Construction




Exterior patch plates




Phase II Rehab Construction



Interior patch plates



Phase II Rehab Construction



Joint welds





Phase II Rehab Construction




Weld Inspection





Phase II Rehab Construction





Coating: Final abrasive blasting






Phase II Rehab Construction



Coating inspection: Chlorides



Phase II Rehab Construction



Coating inspection: Surface profile



Phase II Rehab Construction




Coating: Pit filling





Phase II Rehab Construction



Coating: Interior finish





Phase II Rehab Construction




Coating: Exterior finish





Phase II Rehab Construction





Coating inspection: Film thickness






Phase II Rehab Construction



Coating inspection: Adhesion & holiday testing



Phase II Rehab Construction



Final Inspection





Next Phases

Short Term

- Periodic internal inspection
- Coating repairs to maintain protection

Long Term

- Corrosion-resistant replacement
- Facility modification





Many thanks to:

Massachusetts Water Resources Authority

Stephen Cullen

Michael Barter

Marty McGowan

Andrea Adams

Roberto Jarrin

Charles Ryan

Meredith Norton

Eleanor Duffy

David Pottle

Dan Walton

PPCSO Facility Operators





Many thanks to:

Stantec (Prime Consultant, Phase I Design)

Brian Shea

Kenneth Scully

Michael Carroll

Arcadis (Prime Consultant, Phase II Design)

Jennifer Lachmayr


Stephen Perry

Confined Space Entry Solutions (Rescue)

Arthur Laporte

Leo Stapleton





Many thanks to:

**Hazen and Sawyer
(Prime Consultant, Construction)**

James Barsanti

Jaclyn Lemieux

Engineering Concepts, Inc. (Resident)

Richard Monteiro

Corrosion Probe, Inc. (Subconsultant)

Randy Nixon

Jarod Barbee

Rigo Gomez

Bryce Annino

Mark Gartside





Many thanks to:

R. Zoppo Corporation (General Contractor)

Alex Levey

Franco Nicolazzo

Phil Doherty

Anthony Gratta

DC Welding, Inc. (Welding)

Dan Charko, Sr.

Dan Charko, Jr.

John Charko

Tnemec/Righter Group

Larry Mitkus





Many thanks to:

Mistras (Weld testing)

John Doucette

Bill Davis

John W. Egan Company (Painting)

Robert “Junior” Belisle

Josh Graf

OHS Training & Consulting (Rescue)

True North Safety (Site Health & Safety)





RUNNING BETWEEN RAINDROPS:

Corrosion Repair of a Critical CSO Pump Discharge Pipe



QUESTIONS?

Alejandro Alvarez
Construction Coordinator
Massachusetts Water Resources
Authority

Kevin R. Krawiec, PE
Principal Structural Engineer
Corrosion Probe, Inc.

